

Technical Bulletin

MAYTAG®

Type Policy Letter
√ Service Information

Date: July 2006

Attention Service Managers
√ Service and Parts Managers

No: TDL-0138-B
Page 1 of 1
ITDL-0044-B

Models MAV1655A*, MAV1755A*, MAV208DA*, MAV2755A*, MAV2757A*,
MAV275SA*, MAV308DA*, MAV3757A*, MAV3758A*, MAV3855A*,
MAV385SA*, MAV3905A*, MAV3955E*, MAV4057A*, MAV408DA*,
MAV4500A*, MAV4755A*, MAV4757A*, MAV4758A*, MAV5000A*,
MAV5057A*, MAV551EE*, MAV5736A*, MAV5758E*, MAV5842A*,
MAV5920A*, MAV5920E*, MAV6000A*, MAV6057A*, MAV6200A*,
MAV6257A*, MAV6300A*, MAV6357A*, MAV6451A*, MAV6548A*,
MAV6601A*, MAV7000A*, MAV7057A*, MAV7200A*, MAV7346A*, MAV7357A*, MAV7358A*,
MAV7450A*, MAV7501A*, MAV7504E*, MAV7551A*, MAV7600A*, MAV7636A*, MAV7642A*,
MAV7700A*, MAV7751A*, MAV7757A*, MAV7901A*, MAV8000A*, MAV8057A*, MAV8260A*,
MAV8500A*, MAV8600A*, MAV8751A*, MAV8757A*, MAV9501A*, MAV9600A*, MAV9600E*,
MAV9750A*, MAVT236A*, MAVT346A*, MAVT446A*, MAVT546E*

Brand
Maytag

Product
Laundry

Issue Motor noise resonating from the base frame.

Warranty Standard product manufacturing warranty applies.

Action Add asphaltic pads (SOUND DAMPER - P/N 22001144), to the base to dampen and deaden the motor noise resonating from the base frame. Be sure to clean the areas of the base where the pads go, before installing the pads. The asphaltic pads will need to be cut into appropriate sized pieces to fit on the base frame.

