

Technical Bulletin

MAYTAG®

Type Policy Letter
√ Service Information

Date: June 2003
TDL-0013-B
ITDL-0012-B
No: Page 1 of 1

Attention √ Service Managers
Service and Parts Managers

Models MAV, PAV, CAV —CAV2000AWW, CAV4000AWW, CW5000W, CW6000W, CW6000Q, CW7500W, CW7500Q, DLW231RAW, ALW221RJW, HAV12K2AWW, HAV42K2AWW, PAV2300AWW, PAV2360AWW, PAV3240AWW, PAV3300AWW, PAV3360AWW, PAV4960AWW, PAV5000AWQ, PAV5000AWW, PAV5157AWW, PAV5158AWW, AAV1200AGW, AAV1200AJW, AAV1200AKW, AAV2200AGW, AAV2200AJW, AAV4200AGW, CAV2000AGW, CAV2000AJW, CAV2000AKW, CAV2000AWQ, HAV1200ARW, HAV1200AWQ, HAV1200AWW, HAV4200AKW, HAV4200ATW, HAV4200AWW, LNC6760B71, LNC6762B01, LNC6762B71, LNC6764A71, LNC6766B71, MAV2200AJW, PAV2300AGW, PAV3300AGW, PAV3300AKW

Brand
Admiral
Crosley
Magic Chef
Maytag
Maytag Performa


Product
Laundry

Issue New sheet metal transmission cover.

Warranty Standard manufacturing warranty applies.

Action Manufacturing has made a change in the appearance only of the service and production of the dual drive transmissions. In April 2002, the process of transitioning over to the new style sheet metal cover transmission was initiated. The part change will not affect the internal components of the transmission, and was done to improve the manufacturing process. The part numbers have remained the same with the old style transmission fitting new product and new fitting old.

New Style



Old Style

