

Technical Bulletin

MAYTAG®

Type Policy Letter
ö Service Information

Attention Service Managers
ö Service and Parts Managers

Date: May 2004

No: TDL-0054A-B
ITDL-0023-B
Page 1 of 1
Supersedes TDL-0054-B

Models MAV2200AJW, MAV4057AWA, MAV4057AWQ, MAV4057AWW, MAV4500AWW, MAV5000AWQ, MAV5000AWW, MAV5057AWQ, MAV5057AWW, MAV5736AWW, MAV5842AWW, MAV5960AWW, MAV6000AWQ, MAV6000AWW, MAV6057AWQ, MAV6057AWW, MAV6200AWQ, MAV6200AWW, MAV6250AWQ, MAV6250AWW, MAV6257AWQ, MAV6257AWW, MAV6260AWW, MAV6300AGW, MAV6300AWQ, MAV6300AWW, MAV6300BGW, MAV6300CGW, MAV6357AWW, MAV6358AWW, MAV6451AWQ, MAV6451AWW, MAV6457AWW, MAV6458AWW, MAV6548AWQ, MAV6548AWW, MAV6601AWQ, MAV6601AWW, MAV6650AWW, MAV7000AWQ, MAV7000AWW, MAV7057AWQ, MAV7057AWW, MAV7200AWQ, MAV7200AWW, MAV7257AWQ, MAV7257AWW, MAV7258AWQ, MAV7258AWW, MAV7260BWW, MAV7346AWW, MAV7357AWQ, MAV7357AWW, MAV7358AWW, MAV7450AWQ, MAV7450AWW, MAV7501AWW, MAV7501EWW, MAV7550AWQ, MAV7550AWW, MAV7551AWQ, MAV7551AWW, MAV7557EWQ, MAV7557EWW, MAV7580EWQ, MAV7580EWW, MAV7600ACQ, MAV7600AGW, MAV7600AWQ, MAV7600AWW, MAV7600CGW, MAV7636AWQ, MAV7636AWW, MAV7642AWQ, MAV7642AWW, MAV7650AWQ, MAV7650AWW, MAV7700AWQ, MAV7700AWW, MAV7750AGW, MAV7750BGW, MAV7750CGW, MAV7751AWQ, MAV7751AWW, MAV7757AWQ, MAV7757AWW, MAV7901AWQ, MAV7901AWW, MAV8000AWQ, MAV8000AWW, MAV8057AWQ, MAV8057AWW, MAV8260AWW, MAV8500AWA, MAV8500AWQ, MAV8500AWW, MAV8551AGW, MAV8551AWQ, MAV8551AWW, MAV8557AWQ, MAV8557AWW, MAV8600AWQ, MAV8600AWW, MAV8601AWQ, MAV8601AWW, MAV8751AWQ, MAV8751AWW, MAV8757AWQ, MAV8757AWW, MAV9501AWQ, MAV9501AWW, MAV9501EWQ, MAV9501EWW, MAV9557EWQ, MAV9557EWW, MAV9600AWQ, MAV9600AWW, MAV9600EWQ, MAV9600EWW, MAV9750AGW, MAV9750AWQ, MAV9750AWW, MAVT634AWW, MAVT734EWW, MAVT834AWQ, MAVT834AWW,

Brand
Maytag

Product
Laundry

Issue Outer Tub modification.

Warranty Standard product manufacturing warranty applies.

Action Atlantis model washers have undergone an Outer Tub design modification. In the past the Outer Tub was supplied in black. Current production and service replacement Outer Tubs will be manufactured in the natural resin color, with no black pigment added. This change does not affect the Quality or function of the Outer Tub, and aligns the Atlantis washer with the other Maytag family of washers. While the Outer Tub received for service replacement looks like other Outer Tubs it is unique and correct for Atlantis washers.