

Technical Bulletin



Date: Feb 5 2002

Type Policy Letter
√ Service Information

No: TDL-0002A-B
Page 1 of 1

Attention Service Managers
√ Service and Parts Managers

Brand
Maytag

Models Atlantis models with "Detergent Dispenser Kit".

Issue Liquid detergent dispenser may drip.

Warranty One (1) year part warranty covering defects and workmanship.

Action Order new detergent dispenser **22003797**. Replace old dispenser with new dispenser having a re-designed nozzle clip. The nozzle clip collects residual detergent in the spout area and puts it into the water before the machine ends the cycle. Use the existing torsion rod and retainers not included with the replacement dispenser. For new installations, or to replace entire kit, order "Detergent Dispenser Kit" **22003796**. The "Detergent Dispenser Kit" contains the new dispenser with the re-designed nozzle clip. **Note: The re-designed nozzle clip is not interchangeable with the original detergent dispenser.**

Product
Laundry Product

